

Q. Why is sulphide ore of copper heated in a furnace after mixing with silica?

Ans: Iron oxide present as impurity in sulphide ore of copper forms slag which is iron silicate and copper is produced in the form of copper matte. $\text{FeO} + \text{SiO}_2 \rightarrow \text{FeSiO}_3$.